

# **The Abi from 2011 to 2017**

Yasmine Mahmoud

2017

2011

2011

Filling the gaps in the  
mud layer covering  
the roof of the Abi  
entrance





2011

## Monitoring



Condition of the Abi



2012

2012

## Monitoring

Photos documenting the condition  
of the inside of the Abi





2012

## Monitoring



The Abi after a heavy rain storm



2013

2013

## Monitoring

Damages in the Abi- November 2013





2013

## Maintenance- Abi dome renovation

Damages of the Abi dome, which lead to the replacement of the tarp covering the dome with overlapping metal sheets- December 2013





2013

## Maintenance- Abi dome renovation



Securing the metal sheets

Covering the base of the dome with bitumen



Bending the iron above ventilation shafts to form water drain



2013

**Maintenance- Abi dome  
renovation**



End result

2014



2014

## Maintenance- Abi entrance renovation

Remove dirt layer and tarp covering the  
entrance roof



Damaged roof



2014

## Maintenance- Abi entrance renovation

Remove the metal structure to be fixed and welded, than placed back in its place





2014

## Maintenance- Abi entrance renovation

Covering the metal structure with metal sheets.





2015

2015

**Maintenance- Covering  
Abi dome, half with dirt  
and half with burlap**



2015

**Maintenance- Covering  
Abi dome, half with dirt  
and half with burlap**



The end result of the half and half coverage experiment



2015



New Abi- March 2015



2015

## Repairs

Filling the gaps between the  
stones of the Abi with mud





2015

## Vegetation

Removing the shrubs and  
grass from around the Abi

Before



After



2015

## Monitoring



Abi covered with snow



2016

2016

## Repairs



Torn Curtains



New Curtains



2016

## Vegetation

Removing the shrubs and  
grass from around the Abi



Before



After



2017

2017

## Monitoring

## Condition of the Abi





2017

## Repairs

Replacing the protective curtains



2017

## Repairs

Cleaning inside the Abi





2017

## Repairs

Before painting the dome of the Abi



2017

## Repairs

Cleaning the dome of the Abi from  
dirt and burlap before painting






2017

## Repairs

Mixing the paint and painting the dome



2017

## Repairs

Final results after painting





2017

## Vegetation

Removing shrubs and vegetation  
from around the Abi

Before



← After →

